## PROFORMA FOR THE SAFETY OF SCHOOL BUILDING PART-1

(To be filled by the Head of School/ Institute )

( ~ ~	of the treat of behoof histiate)			
1.	Name of the School	: VICTOR	A PUBI	1c Scho
2.	Location	: V.P.U. L.	ZHRA, O	12-1-2-udh
3.	Plot Area	: 9940		
4.	Plinth Area	: 3668 S	2 Youd	33012 FT
5.	Number of Storey's	: Thace (		
6.	Year of Construction of Building	: 2005,07	,08,12	and 15
7. a)	If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given Name of the Engineer with qualification		Attac	
b)	Address of Engineer		h = -x	
c)	Set of Structural drawings used in the construction, if available	: 11		
d)	Name & address of Architect with qualification	:		
8.	Whether the building has been constructed for the purpose	•		
a)	School	: YE	S/NO	Yes.
b)	Residential Purpose and converted for use as a School		S/NO	No
9.	Materials used for roofs			
a)	R.C.C. Slabs/R.B.C. Slabs	: YE	S/NO	705
b)	R.S. Joist & Battons	: YE	S/NO	No
c)	Wooden joists & Battons	: YE	S/NO	No
10.	Materials used for walls			
a)	Mud Mortar	: YE	S/NO	No
b)	Cement Mortar	: YE	S/NO	Yas
c)	Lime Mortar	: YE	S/NO	No
11.	Flooring			
a)	Conglomerate	· YE	S/NO	Yas
b)	Terrazo	: YES	S/ NO	No
c)	Brick Paving.		SINO	No
12.	A detailed drawing indicating dimensions of the rooms Alongwith size and location of doors and windows	A Baji an iyo dhubu		

Victoria Public School Ahmedgarh-khera Road, LEHRA (LDH.)

Affiliation No.: 1630545, School Code: 20534 M 98554-61951

(Attached)

Signature with Stamp of the seal Of the School Institution School Ahmedgam-Khera Road, LEHRA (LDH.

Afficiation No.: 1630545, School Code: 2053/ M -0955 : 310-

Sat Sanit Educational Trust (Regd.) Ahmeugarn (Sangrur)

## Part-II (To be filled by S.D.E of P.W.D B&R Department) **Building Safety Report**

Name of School: NICTORIA VUBLIC SCHOOL, Ahmazjorh-xhara Road, 20hea, Lydhio

I have visited the above mentioned School building along with Sh. Six on dated 05. 4.24 and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a. Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details Structural Drawings, Technical Specifications, Test Reports of Material used Quality Control reports and Certificate from Engineer in Charge for Construction are not available.
- b. In case of any addition, alteration of expansion and modification of this building are done; certificate may be re-obtained after completion from undersigned.
- c. In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check · the stability and safety of the building.
- d. A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- A separate certificate regard Electrical Work should be obtained from the competent authority.
- The owner of the building/Management is fully responsible regarding safety of building from all angels in spite of this report.
- The covered area of the building is .33012 SFT
- h. This report is not valid for legal purpose.
- As per Government order no. 5/13/2018-3BR3/1294287/3 dated 10-08-2018 for issue of building safety certificate Para 2.0 (a), this certificate as requested by school authority is issued for period of 4 years up to 31-03-2028 [March 2028

Junior Engineer

Perept No 10988870

Date 09/04/24

Ahmeogam (Sangror)

Victoria Public School Ahmedgarh-khera Road, LEHRA (LDH.) Affiliation No.: 1630545, School Code: 20534

M · 98554-61951